

NPIC/TDS/D-743-67
13 March 1967

MEMORANDUM FOR THE RECORD

SUBJECT: Chip Comparator Failure; Project 997434

1. On 13 March the 405A Chip Comparator Y axis interferometer stopped functioning while I was performing a repeatability test. [] checked and found that there was no signal from the photomultiplier. I have contacted [] and we are arranging to have their personnel come down and repair it.

STATINT

2. In the event that the trouble is not covered by warranty but is a problem of an expendable component, T. [] has agreed to cover the costs through a reconfirming requisition.

STATINTL

STATINT

[]
Support Systems Branch, TDS/DS

Distribution:

Original - Route & File
2 - TDS/DS

DECLASS REVIEW by NIMA/DOD

~~STATINTL~~
Approved For Release 2002/06/17 : CIA-RDP78B04747A001500030029-2

Approved For Release 2002/06/17 : CIA-RDP78B04747A001500030029-2